

Merchants Bonding Company



Merchants Bonding Company

Table of Contents

- Safe Hours
- Current Highlights
- Project Pictures
- Upcoming Highlights



Safety

63,128
Safe Hours
to Date



Current Highlights

- Final Cleaning Complete
- Sod Installation Ongoing
- Furniture Installation Complete
- Audio and Visual Equipment Installation Ongoing
- Certificate of Occupancy Received
- SUBSTANTIALLY COMPLETE ON 7/31/15!



Merchants Bonding Company

Certificate of Occupancy Received



Merchants Bonding Company

Sod Installation Has Begun



Merchants Bonding Company

Landscaping at South Entry Complete



Merchants Bonding Company

Landscaping at Grandma's Garden Complete



Merchants Bonding Company

North Entry



Merchants Bonding Company

Reception Desk and Monument Stair at Atrium



Merchants Bonding Company

First Floor Waiting Area



Merchants Bonding Company

Fitness Room



Merchants Bonding Company

Training Room



Merchants Bonding Company

Café Looking West



Merchants Bonding Company

Treat America Food Service Equipment in Place



POS System



Merchants Bonding Company

Kitchen Appliance Installation Complete



Merchants Bonding Company

Board Room Casework and Fridge Installation Complete



Fridge with
custom
wood face



Merchants Bonding Company

Board Room



Looking East



Looking West



Merchants Bonding Company

Open Office



Merchants Bonding Company

Typical Meeting Room




Merchants Bonding Company

Glass Film Installed at Private Offices




Merchants Bonding Company

Typical Private Office



Merchants Bonding Company

Soft Seating at Second Floor West



Merchants Bonding Company

Upcoming Highlights

- Sod Installation and Seeding
- FIRST WAVE OF OWNER MOVE IN 8/7/15
- SECOND WAVE OF OWNER MOVE IN 8/14/15





**Congratulations to
Merchants Bonding
Company on your new
Corporate
Headquarters!**

Ryan Companies would like to thank all those involved with this project for their effort in making this project a success!!

